

KDC Driver Installation (Windows XP, Windows7, Windows 8)

WARNING: DO NOT CONNECT THE KDC TO THE USB PORT PRIOR TO INSTALLATION

- Download and uncompress a zip file into your computer.
- Click on the Setup.exe file which executes the KDC Driver Setup Wizard.


NOTES


- If the KDC Driver Setup Wizard locates an older version of the KDC Driver on your computer, you will be prompted to remove the older program before installing the new version. Select Remove KDC Driver, and then click Finish. When removal is complete, click Close.

KDC Driver Setup Wizard


Below are the screen images you will see during the installation of the KDC driver.

- **Click Next icon in KDC Driver Setup Wizard window**






- **Click the Close icon in the KDC Driver Installation Complete window and wait for Device Driver Installation Wizard**



- Click **Install This Driver** in the **Windows Security** window and the installation is finished.



Connect KDC to Computer

Using the USB cable included with the KDC, follow the directions below.

- Connect the ultra mini USB connector to the KDC.
- Connect the Type A USB connector to your PC.
- Wait until your computer beeps and/or displays the message Found New Hardware.

Verify COM Port Address

- User can verify installed COM Port in Device Manager

